San Jacinto River Waste Pits Superfund Site






Temporary Cap Construction Completed July 2011

Overview of Damaged Area

- Prior to repair paper mill waste containing dioxin was exposed to environment.
- Cause of damage unknown & under investigation.
- Cap repairs completed Jan 4.
- Site is securely fenced & access prohibited.
- Quality assured data confirmed surrounding cap areas remain protected.



EPA Dive Team inspection - Dec 2015




Areas investigated by EPA Dive Team



Dive Team inspection Results



Probing to define damaged rock area






Shallow sample from damaged cap.



Placing geotextile over damaged area



Placing rock over geotextile in damaged area




Repair completed at low tide - Jan 2016

Next

New Safety Requirements

- Add 24/7 surveillance.
- Add warning buoys.
- Enhanced inspections & double frequency.



Draft Site Buoy Enhancements Plan


EPA Requiring Additional Sampling:

- Armor cap sampling.
- Sediment sampling
- Surface water sampling
- Ground water sampling.

U.S. Army Corps of Engineers Assistance Will:

- Further investigate cause of damaged area.
- Recommend additional inspection requirements (by end of April).
- Recommend actions to prevent future occurrences (by end of April).

EPA Will direct PRPs to perform additional actions based on Corps findings.



San Jacinto River Waste Pits Superfund Site For More Information:

U.S. EPA

Gary Miller

Remedial Project Manager

(214) 665-8318 or (800) 533-3508

Donn Walters

Sr. Community Involvement Coordinator / Public Liaison

(214) 665-6483 or (800) 533-3508

Site Repository:

Highlands Public Library, Stratford Branch 509 Stratford Street, Highlands Texas

Texas Commission on Environmental Quality

Satya Dwivedula

Project Manager

(512) 239-3548

Crystal Taylor

Community Relations

(512) 239-3844

